



Contribution ID: 17

Type: **not specified**

Pinhole Camera issues at Diamond

Tuesday, 16 June 2015 10:00 (15 minutes)

Our Pinhole assembly has clogged up frequently with ‘something’, possibly Tungsten Oxide. We have explored a variety of mitigations (including those used at other labs) and will report on success and failure.

Primary author: Ms BOBB, Lorraine (Diamond Light Source)

Presenter: Ms BOBB, Lorraine (Diamond Light Source)